


| Block | Lot | QUAL. | Area | Address |
|---|---|---|---|---|
| 21.02 | 22.01 | C01 | 1,588 S.F. | 6 HARRIS ROAD |
| 21.02 | 22.01 | C02 | 1,588 S.F. | 8 HARRIS ROAD |
| 21.02 | 25.01 | C01 | 1,588 S.F. | 4 HARRIS ROAD |
| 21.02 | 25.01 | C02 | 1,588 S.F. | 2 HARRIS ROAD |
| 7101 | 3.01 | C01 | 1,440 S.F. | 12 HARRIS ROAD |
| 7101 | 4.01 | C01 | 1,440 S.F. | 14 HARRIS ROAD |
| 7101 | 5.01 | C01 | 1,440 S.F. | 18 HARRIS ROAD |
| 7101 | 5.01 | C02 | 1,440 S.F. | 16 HARRIS ROAD |
| 7102 | 3.01 | | 1,216 S.F. | 293 WITHERSPOON ST |
| 7102 | 3.02 | | 1,216 S.F. | 295 WITHERSPOON ST |
| 7108 | 21.01 | | 1,565 S.F. | 120 JEFFERSON RD |
| 7108 | 21.02 | | 1,460 S.F. | 118 JEFFERSON RD |
| 7109 | 9.01 | | 1,440 S.F. | 135 JEFFERSON RD UNIT 1 |
| 7109 | 9.02 | | 1,440 S.F. | 133 JEFFERSON RD UNIT 2 |
| 7109 | 10.01 | | 1,440 S.F. | 137 JEFFERSON RD |
| 7109 | 10.02 | | 1,440 S.F. | 139 JEFFERSON RD |
| 7110 | 6.01 | | 1,500 S.F. | 173 JEFFERSON RD |
| 7110 | 6.02 | | 1,500 S.F. | 175 JEFFERSON RD |

This map has been redrawn using Computer Aided Drafting/Design (CAD/D) based on the maps prepared by Matthew L. Martini, December, 1994 and Kenneth R. Raike, August, 2011.

| REVISIONS | | |
|---|---|---|
| DATE | NAME | NO. |
| 10/1/14 | GREGORY SANDUSKY | GB36758 |
| 10/1/15 | GREGORY SANDUSKY | GB36758 |
| 10/31/16 | GREGORY SANDUSKY | GB36758 |
| 10/1/17 | GREGORY SANDUSKY | GB36758 |
| 10/1/18 | GREGORY SANDUSKY | GB36758 |
| 10/1/19 | GREGORY SANDUSKY | GB36758 |

THIS MAP SHEET HAS BEEN FORMALLY CERTIFIED FOR CONSOLIDATION ON 12/10/2012, ASSIGNED SERIAL NUMBER 1012, AND SIGNED BY SUE DAVIDSON (CTA SUPERVISING FIELD REPRESENTATIVE FOR THE STATE OF NEW JERSEY). A COPY OF THE ORIGINALLY APPROVED MAPS ARE ON FILE AT THE MUNICIPALITY OF PRINCETON LOCATED AT 400 WITHERSPOON STREET, PRINCETON, NJ. THE NEW JERSEY STATE DIVISION OF TAXATION IS RETAINING THE OFFICIAL APPOVED MAPS.

# TAX MAP
# PRINCETON

MERCER COUNTY, NEW JERSEY

SCALE: 1" = 100' OCTOBER, 2012

DAVID B. DIXON, PLS

Professional Land Surveyor N.J. Lic. No.27282

OMLAND ENGINEERING ASSOCIATES, INC.

CEDAR KNOLLS, NEW JERSEY

To Show Conditions as of October, 2012